


#43260
Replacement thread on
heavy duty stallcock for BM



ITEM	PART NUMBER	Description	Qty
1	43238	Rubber cap	1
2	43239	Ball	1
3	18067	Gasket	1
4	43236	Repair kit for BM stallcock (Includes: 2-4)	1